SAPC- 12607 Copy ? of 5

28 January 1957

Dear Burt:

Reference is made to my telephone conversation with you concerning Sid's System III antenna design and location.

You are requested to consider this letter as your authorisation to proceed with the work necessary to make the new location and design of the antenna compatible with your System. III. It is my understanding that this work involves approximately one man week of engineering and four man weeks of technician time to develop the proper impedance for the cabling.

Yours very truly,

George

SA/PC/DCI/JMcD:pf (1/28/57)

Distribution: 25X1A

Orig -∠ Cy 2 - [(corres) 3 - FOG file 4 - Chrono

25X1A

DOCUMENTING. NO CHANGE IN CLASS. O DECLASSIFIED CLASS CHARGED TO: TS S C NEXT REVIEW DATE: ____

Approved For Release 2002/06/13: CIA-RDP81B00878R000300040020-8

143/17

Approved For Release 2002/06/13: CIA-RDP81B00878R000300040020-8

SAPC / 26// COPY / OF /

11 January 1957

Dear George:

In reference to Russ' letter of 2 and 7 January, regarding our System 3 antenna design, Burt has called us and agreed to do the work. He said it would take about one manweek engineering and four manweeks technician time. Please authorize him to proceed.

25X1A

Jim gler with a mit & But reference my withen and state this in written and there is the formal. Centrail 18-101, FOG reg. for sign.

_	maybe "	
	Approved For Release 2002/06/13 : CIA-l	RDP81B00878R000300040020-8 / 2 2 5 2
	D&P	2 January 1957
		2 January 1057
	111/5-7	~ balldary 17)?
	Dear George:	
e e e e e e e e e e e e e e e e e e e	in our four special articles. It ce the rear fin as the principal recep semicircular hole approximately eig	tor. This requires Kelly to cut a ht inches in diameter through the area with a non-conducting material. Alling edge of the fin he must also from the bottom. This essentially
	Our man discussed fabrication of Burt's antenna men. Henry said his problem and he is ready to go. a model, which Henry has already sen and make a matched lead. Since this little touchy with Burt, I asked him to do it without interfering with Symagnitude of the job. He said the whe did not think it would cause any another call which he has not given ance should take no more than one man	part of the fabrication is no said he could cut the hole in him, measure the impedence particular antenna work is a to confirm by phone his ability ystem 4 and for an estimate of the whole thing looked reasonable and trouble; however, he promised me Our man says matching the imped-
		7 January 1957
/ /~a	so we can get going? If they don't Field, but the three parties, Henry, that the job is so small it should to the pechange in class. If they don't henry, the pechange is class.	e cone on the West coast for convenience.
11/5-7 Ducu	AUGGE HR 70-2 ATEV THE REPORT OF THE PROPERTY	e tolay ho actum on ince hus o 12W hora
in fa	of weed on of more me	nee Kus + 1EW k-12
El.	4/57	25X1A
A-	101 ACC	jele de
Zy 2 -	Approved For Release 2002/06/13 : CIA-I	RDP81B008796000300040020-8

25X1A

25X1A

25X1A

25X1A